IN THE DRAWINGS:

The attached sheet of drawings shows changes to Figure 1. Particularly, Applicants have deleted the reference sign "140" positioned below the words "TO CONTROLLER." That reference sign is out of place and an obvious drafting error.

Attachment:

Replacement Sheet for Figure 1

Annotated Sheet Showing Changes to Figure 1

REPLACEMENT SHEET
ATTY DKT. No.: AMAT/6339/CMP/CMP/RKK

U.S. SERIAL NO.:

FILED: TITLE:

RIAL NO.: 10/056,316 CONF. NO.: 2

JANUARY 22, 2002

ENDPOINT DETECTION FOR ELECTRO CHEMICAL MECHANICAL
POLISHING AND ELECTROPOLISHING PROCESSES

PAGE 1 of 5

CONF. No.: 2878

1/5

